


A photograph of a wooded area. In the foreground, the ground is covered with a thick layer of dry, brown leaves and some small green plants. A large, dark tree trunk is visible on the right side. In the background, a chain-link fence runs across the frame, with more trees and foliage behind it. The scene is lit by natural light, creating shadows on the ground.

[illegible][illegible][illegible]



⑦実習棟山側～部室間

実習棟から部室等へ続く 側溝で暗渠になっている 箇所 (写真のとおり)
--



⑧部室裏

側溝に蓋無

